

Contact to

WEB : http://www.shinkawa.co.jp/

SHINKAWA Electric Co., Ltd. 3rd Fl. Shin-kojimachi Bldg.3-3 Kojimachi 4-chome, Chiyoda-Phone : 81-3-3263-4411 Fax : 81-3-3262-2171 okyo 102-0083 Japar

SEC of America Inc. 4355 Ferguson Drive Ste. 215, Cincinnati, Ohio 45245, USA

Phone: 1-513-453-4560 Fax: 1-513-297-9003 email: info@sec-america.com WEB: http://www.sec-america.com

SHINKAWA Sensor Technology, Inc.

4-22 Yoshikawa-kogyodanchi, Higashihiroshima 739-0153, Japan Phone : 81-82-429-1118 Fax : 81-82-429-0804 WEB : http://www.sst-shinkawa.co.ip

\* Specifications, outline drawings and other written information can be changed without notice.

Published in Mar. 2009





Monitors or signal converters are unnecessary. Electric current output makes long wiring possible. **Direct connection to control instruments.** The ideal system for monitoring small compressor vibrations.



# 2-wire TRANSMITTER



SHINKAWA Sensor Technology, Inc.

## SIMPLE WIRING -2-WIRE TRANSMITTER

• The WK series transmitter is an eddy-current type transmitter that incorporates vibration converter features, supplying the power and transmitting the signal with a 2-wire current loop. The WK system reduces equipment and wiring costs. Two kinds of transmitters are available - the WK-142K for shaft vibration, and the WK-142T for thrust position.

Monitors or vibration converters are unnecessary. Electric current output makes long withing possible. **Direct connection to control instruments.** The ideal system for monitoring small compressor vibrations.

Example of SYSTEM CONFIGURATION



### Outline Drawing

### Specifications WK-142K WK-142T **WK Transmitter** BNC Connector 4 to 20mA 0 to 100 µm pk-pk, -0.6 to 0 to +0.6 mm. -0.635 to 0 to +0.635 mm Name Plate 0 to 125 µm pk-pk, **Output Range** Sensor Connector Terminal 0 to 200 µm pk-pk, 0 to 250 µm pk-pk, 0 to 400 ...m pk-pk 0 0 • 4.5% of full scale range • (from test signal input pin to current output) (from test signal input pin to current output) 4 to 20mA Output Conversion Accuracy POWER/OUTPUT 74(2.91) Max. Load Resistance 43.5• (Vps-12)• (Vps=Power supply voltage) **ଚ** Calibration Material JIS SCM440 flat (AISI 4140 equivalent) Ð GAP OUT **I**A 1.4 mm (Gap : 0.3 to 1.7 mm) Linear Range\* Scable Factor\* 7.87 mV/μm $\bigcirc$ 5 m, 7 m system : 7.87 mV/µ.m• 6.5% typ. (including interchangeability errors) 8 Scale Factor Error\* 9m system : 7.87mV/µm• 40% typ. (including interchangeability errors) 100 (3.94) Step : 200 µm, Target : 30 mm dia. Output Impedance\* 10 k• •(it is calibrated load impedance at 10 M• ) Frequency Response\* 5 Hz to 6,000 Hz (• 0 dB, • 3 dB) Ref (66 at 900 µm Gap (2.36) 50(1 Transmitter : 0 to 70. Operatina Temperature Range Sensor & Extension cable : • 84 to • 477• •(Connector : Max.125• ) Relative Humidity 95% RH (non-condensing) Power Supply Voltage 12 to 35 VDC DIN Mounting Clip (Option) System Cable Length 5 m, 7 m or 9 m 5 m. 7 m Dimensions : mm (inch) \* The above specifications apply at 25. with 24 VDC power supply and SCM440 (AISI 4140 equivalent) Model Code steel flat target. >WK-142K - //NB1 /DNC /CEM For Shaft Vibration System Cable Length Output Range Non-incendive With DIN Mounting Clips CE Marking 1 0 to 100 µm pk-pk 5 m CSA : Class I Div.2 Gr. A,B,C,D ATEX : EEx nA II T6 7 m 2 0 to 125 µm pk-pk 2 3 0 to 200 µm pk-pk 5 9 m 4 0 to 250 µm pk-pk

5 0 to 400 µm pk-pk

For Thrust Position

	System Cable Length			Output Range		
	1		5m	1	-0.6 to 0 to +0.6 mm	ſ
Į	2		7m	2	-0.635 to 0 to +0.635 mm	1
				2	(-25 to 0 to +25 mils)	ľ

### **Outline Drawing and Model Code**

**WL Sensor** 

L





## Coax. Connector Sensor Side

WW Extension Cable



1



----